




VT0-1 >>> Retrofit Opportunities



High temperature execution CPVC fill



Steel drift eliminators



Oversized motor & Drive set



Discharge hood



- Improve maintenance and accessibility
- Enhance operational safety
- Reduce sound emission
- Save water
- Save energy and increase performance
- Increase reliability



External platform with ladder & casing railing



Clean out port



BCP automatic bleed control




Separator



Basin sweeper piping



Plume abatament coil




Fan guard



Intake & discharge attenuation



Baltiguard (standby motor & motor base)



Heater package



Electric water level control package

Note: The drawings on this page are for reference only, and may vary from the actual solution offered.