


Vibration cut out switch

Spare parts guide

Vibration cut out switch

- The switch **detects excessive fan drive vibration** caused by fan icing or any mechanical fault.
- Mechanical operation with multiple options for alarms and reset.
- Guarantees year-round reliable and safe operation.





Downloads

• The SERVICE EXPERT for BAC Equipment